



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 20, 2008

Reviewed: 7

Mine Name: Hurricane Sandstone	Permit Number: S/053/0077
Operator Name: Feller Enterprises (Allen Feller)	Inspection Date: April 10, 2008
Inspector(s): Lynn Kunzler	Time: 5:30 pm
Other Participants: None	Mine Status: Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

The Division received the Notice for this operation on July 11, 2005. To date this operation has not received approval, nor has the operator provided a reclamation surety for this proposed 2 acre site.

This area is adjacent to the R&W Excavation site. in 2006, an agreement was made and the permit boundary between to two sites was marked (this boundary was not apparent during this inspection). Without knowing where this boundary is, it is impossible to tell if there has been activity on this permit area..

Photos were taken to document site conditions.

Conclusions and Recommendations:

The operator is reminded of the need to maintain the permit boundary between the two permits. The operator also needs to finalize this permit (deficiency letter sent October 5, 2005), and submit the reclamation surety and contract. If at a later date it is determined that the operator is operating without a permit, enforcement action will be warranted.

Inspector's Signature LKpb

LKpb

cc: Allen Feller, Operator
Russ Schreiner, BLM, St George FO UTU-080545
O:\M053-Washington\S0530077-HurricaneSandstone\inspections\Insp-04102008.doc